

Архангельск (8182)63-90-72
Астана (7172)727-132
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06

Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16

Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13

Сургут (3462)77-98-35
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

Киргизия (996)312-96-26-47

Россия (495)268-04-70

Казахстан (772)734-952-31

www.panblast.nt-rt.ru | | pav@nt-rt.ru

Технические характеристики на устройства переработки абразива маленьких объемов КОМПАНИИ **PanBlast**



Pow Air Vac Assembly



Product Features

The PanBlast™ Pow Air Vac assembly is a manually operated vacuum system for cleanup of small amounts of residual blasting abrasive and/or dust.

- ▶ Air powered - no electrical power required.
- ▶ Powerful twin venturi system for maximum efficiency.
- ▶ Heavy duty ribbed 44 gallon (200 l) steel drum included.
- ▶ 10 m (33 ft), wear resistant abrasive recovery hose.
- ▶ 38 mm (1-1/2") pick up wand standard.
- ▶ Recovers steel grit at up to 1,000 kg (2,200 lbs) per hour.
- ▶ Supply air required: 150 cfm (71 l/second) at 100 psi (690 kPa).
- ▶ Shutoff ball valve standard.
- ▶ Replaceable discharge dust bag.

Common Applications

- ▶ Reduce costs by recovering and recycling expensive abrasives.
- ▶ Reduce clean up operations.

Complementary Products



BP50-1 Blast Pot



BP110-1 Blast Pot



BP316-1 Blast Pot



BP600-1 Blast Pot



Galaxy Blast Helmet




AER215 Nuovo Vacuum Blaster



ProFlo Recycling System



UltraFlo Recycling System



Component Highlights



1 Twin Molded Air Venturis

2 Exhaust Air Diffuser

3 Heavy Duty 200 Liter
Abrasive Media Storage Drum

4 10 m (33 ft) Abrasive Pick Up
Recovery Hose






5 Abrasive Media Pick Up Nozzle

6 Needle Felt Dust Filter

7 Positive Lid Seal


8 19 mm (3/4") Main Air Inlet Ball Valve

9 Compressed Air Manifold



Assembly

Stock Code	Description	Weight	Include Items
BAC-RV-0187-00	Pow Air Vac Top Head	18.5 kg (40.8 lbs)	22
BEC-RV-0127-00	Pow Air Vac Top Assembly	25.7 kg (56.7 lbs)	18 19 20 22
BEC-RV-PB-0001	Pow Air Vac Assembly	51 kg (112.4 lbs)	18 19 20 21 22
BAC-RV-PB-0018	Pow Air Vac Drum Clamp Kit	13.3 kg (29.3 lbs)	23



Parts List



Description	Qty	Description	Qty	Description	Qty
1 PAV Lid	1	8 Hose Clamp	1	15 Spring Washer	4
2 PAV Air Jet	2	9 Nipple	1	16 19 mm (3/4") Ball Valve	1
3 PAV Manifold	1	10 Screw	3	17 Foam Rubber	2 m
4 PAV Venturi	2	11 Flat Washer	3	18 PAV Pick Up Wand	1
5 PAV Venturi Cover	1	12 Spring Washer	3	19 Hose Clamp	2
6 PAV Cage	1	13 Hex Head Bolt	4	20 Pow Air Vac Hose - 10 m	1
7 Dust Bag	1	14 Flat Washer	4	21 PAV Drum	1

Архангельск (8182)63-90-72
Астана (7172)727-132
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06

Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81

Киргизия (996)312-96-26-47

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16

Россия (495)268-04-70

Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13

Казахстан (772)734-952-31

Сургут (3462)77-98-35
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

www.panblast.nt-rt.ru | | pav@nt-rt.ru