

Архангельск (8182)63-90-72
Астана (7172)727-132
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06

Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81

Киргизия (996)312-96-26-47

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16

Россия (495)268-04-70

Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13

Казахстан (772)734-952-31

Сургут (3462)77-98-35
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

www.panblast.nt-rt.ru | | pav@nt-rt.ru

Технические характеристики на мониторы СО и сигналы тревоги, аксессуары компании PanBlast

Виды товаров (аксессуары): калибровочные клапаны в сборе, испытательный газ без примесей, регуляторы фильтра, предохранители, датчики и др.



AirScan Mobile CO Monitor Alarm



Complementary Products



Titan II SAR



Cosmo SAR



Aurora LED Helmet Light



PBF II-1 Airline Filter



PBF II-3 Airline Filter



Respirator Airline Hose



VisiFlo Standard Airline Filter



VisiFlo Premium Airline Filter



Product Features

The PanBlast™ AirScan Mobile Carbon Monoxide Alarm monitors breathing air flow and provides early warning on the presence of any carbon monoxide.

- ▶ Integral Visual and Audible Alarm.
- ▶ Flow Indicator.
- ▶ Status Indicator.
- ▶ Internal Pressure Regulator.
- ▶ Multi Voltage Operation (240/120 VAC, 12 VDC).
- ▶ Calibration Adjustment.
- ▶ Sample Airflow Alarm.
- ▶ Carrying case.
- ▶ Optional remote alarm system, with strobe, siren and 66ft (20m) cable.

Common Applications

- ▶ Protection of blast hose operators.
- ▶ Standards compliance in blasting operations.

PanBlast™ AirScan Mobile CO Monitor and Alarm

Stock Code	Description
BAC-AF-0268-00	AirScan Mobile CO Monitor
BAC-AF-0272-00	AirScan Mobile Remote Alarm

PanBlast™ Accessories/Replacement Parts

Stock Code	Description
BAC-AF-0269-00	Calibration Valve Assembly
BAC-AF-0270-00	CO Test Gas
BAC-AF-0271-00	Impurity Free Air Test Gas
BAC-AF-0341-00	AirScan Sensor
BAC-AF-0342-00	Filter Regulator
BAC-AF-0343-00	AirScan Fuse

Technical Data

Detection Level	10ppm*
Sensor Type	Metal Oxide
Alarm Horn	98db
Power	120 VAC/240 VAC/12 VDC Field Changeable
Approvals	Federal OSHA title 29, Section 1910.134(d) (1) & (2)
Length	270 mm (10.6")
Width	246 mm (9.7")
Height	123 mm (4.8")
Weight	2.27 kg (5 lbs)

* Federal OSHA regulations Title 29, Section 1910.134(d) (1) & (2) specify a maximum concentration of 10ppm carbon monoxide for Grade D air as published in ANSI/CGA Standard G-7.1.



Right side showing power cable and sample air input point



Left side showing audible alarm horn



Optional remote alarm



Top side showing visual alarm indicator

Архангельск (8182)63-90-72
Астана (7172)727-132
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06

Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81

Киргизия (996)312-96-26-47

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижегород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16

Россия (495)268-04-70

Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13

Казахстан (772)734-952-31

Сургут (3462)77-98-35
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

www.panblast.nt-rt.ru | | pav@nt-rt.ru